## National Transportation Safety Board NTSB ID: DEN02LA025 Aircraft Registration Number: N4649J FACTUAL REPORT Occurrence Date: 02/17/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 81301 0920 **MST** Durango Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary

Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Cessna

Aircraft Manufacturer

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 17, 2002, approximately 0920 mountain standard time, a Cessna 172N, N4649J, was substantially damaged when it struck terrain following a loss on control during landing at Animas Air Park, Durango, Colorado. The student pilot, the sole occupant aboard, was not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the local training flight being conducted under Title 14 CFR Part 91. The flight originated approximately 0900.

Model/Series

172N

According to the pilot's accident report, he made one touch and go landing on runway 19. On the second touch and go landing, he overcorrected for a slight right crosswind. The airplane departed the right (west) side of the runway and struck a 3 foot tall pile of dirt, and the left main gear collapsed. The airplane traveled back across the runway and came to rest on the east side of the runway. The airplane sustained substantial damage to the underside of the fuselage, left horizontal stabilizer, and elevator. In addition, two runway lights were broken. The pilot said, "I had slept poorly the previous two nights and in retrospect, I believe fatigue was a significant factor in this accident."

At 0953, the recorded wind condition at Durango-La Plata County Airport, Durango, Colorado, located 8 miles southeast of the accident site, was 100 degrees, at 4 knots.

Type of Aircraft

Airplane

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA025

Occurrence Date: 02/17/2002

AVIATION			rrence Type	e: Accident								
Landing Facility/Approach Information												
Airport Name	Airport ID:	Airport Eleva	Airport Elevation Runway L		way Used	Runway Length		th [	Runw	ay Width		
Animas Air Park 00				6684 Ft.	. MSL	19		5010	0		50	
Runway Surface Type: Asphalt												
Runway Surface Condition: Dry												
Type Instrument Approach: NONE												
VFR Approach/Landing: Touch and Go												
Aircraft Information												
Aircraft Manufacturer Cessna			Mode 172	el/Series N					Serial Number 17273658			
Airworthiness Certificate(s): Normal												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No Nu	Homebuilt Aircraft? No Number of Seats: 4					Certified Max Gross Wt.					r of Engines: 1	
Engine Type: Reciprocating	_	Engine Manufacturer: Model/Series: Lycoming O-320-H2AD						Rated Power: 160 HP				
- Aircraft Inspection Information												
Type of Last Inspection			Date of La	Date of Last Inspection Time Si			nce Last Insp		Airfram	e Tot	tal Time	
Annual			02/2002	02/2002					ours		9:	331 Hours
- Emergency Locator Transmitter (EL	T) Information											
ELT Installed? Yes	ELT Operate	ed? Yes	3		ELT	Aided in	n Locating A	ccident S	Site? No	)		
Owner/Operator Information												
Registered Aircraft Owner	Street	Street Address P.O. Box 1797										
Gregg Flying Sevice	City Durango							State	- 1	Zip Code 81302		
Operator of Aircraft	Street Address Same as Reg'd Aircraft Owner											
Same as Reg'd Aircraft Owner	City							State	;	Zip Code		
Operator Does Business As:				O	perator Desig	gnator Co	ode: IKJ	JA				
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): O	n-demand Air T	Гахі										
Operating Certificate:	cate:											
Regulation Flight Conducted Under: F	Part 91: Genera	al Aviati	on									
Type of Flight Operation Conducted: I	nstructional											
		FACTI	IAL REPO	ORT - AVIATI	ION							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA025

Occurrence Date: 02/17/2002

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name	City				Sta	ate	Date of Birth	Age				
On File On Fil							е			n File	On File	34
Sex: M Seat Occupied	wn	Certificate Number: On File										
Certificate(s): Student												
Airplane Rating(s): None												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): None												
Instructor Rating(s): None												
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review?												
Medical Cert.: Class 3	Medica	al Cert. Statu	s: Valid Med	dicalw/ wa	ivers/lim			Date o	f Last M	Medical E	Exam: 11/2001	
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Ins Actual	Instrument tual Simulat		Rotorcraft	Glider	Lighter Than Air
Total Time	otal Time 38		38									
Pilot In Command(PIC)	10	10	10									
Instructor						$\dashv$						
Last 90 Days	11	11	11									
Last 30 Days Last 24 Hours	4	4	4			+						
Seatbelt Used? Yes	T	nxicolo	oav Perfa	ormed? N	 lo	Is	Eecond Pilot? No					
Coalbon Cood: 100	1 01100	ılder Harness	0300: 163		1.		991 0110	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			7000114 1 1101. 140	,
Flight Plan/Itinerary												
Type of Flight Plan Filed: No	one											
Departure Point					S	State Airport I		rport Iden	ort Identifier		arture Time	Time Zone
Same as Accident/Incide	ent Location					00C						MST
Destination	S	State Airport			tifier							
Same as Accident/Incide		00C										
Type of Clearance: None												
Type of Airspace: Class G												
Weather Information												
Source of Briefing: Unknown												
Method of Briefing: Unkno	own						_		_	_		
FACTUAL REPORT - AVIATION Page 3												

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DEN02LA025

Occurrence Date: 02/17/2002

	ETYBOP	Occurrenc	Occurrence Type: Accident										
Weather Information													
WOF ID	Observation Time	Time Zone	WOF Elevati	ion	WOF Di	WOF Distance From Accid				Direction From Accident Site			
DRO	0953	MST	6684 Ft.	. MSL			NM	Deg.			Mag.		
	st Cloud Condition: Clear			<u>.</u>				of Light: Day					
	eiling: None	Ft.	AGL	Visibi	ility:	10	) SM A		timeter: 30.04		"Hg		
Temperatu	-4 °C							nsity Altitude:	6959	Ft.			
· ·		-4 0									ı ı.		
Wind Spee		Weather Condtions at Accident Site: Visual						itions					
Visibility (R	RVR): Ft.	Visibility (RV	/V)	SM Intensity of Precipitation:									
Restrictions to Visibility: None													
Type of Precipitation: None													
Accident	Information												
Aircraft Dar	mage: Substantial		Aircraft Fir	Aircraft Fire: None				Aircraft Explosion None					
Classificati	ion: U.S. Registered/U.	.S. Soil											
- Injury Sur	mmary Matrix	Fatal Seri	rious Mino	or	None	TOTAL							
First Pil	lot						]						
Second	d Pilot						1						
Studen	it Pilot				1	1	1						
Flight II	nstructor						1						
Check I	Pilot						1						
Flight E	Engineer						1						
Cabin /	Attendants						1						
Other C	Crew						1						
Passen	ngers						1						
- TOTAL A	ABOARD -				1	1	1						
Other G	3round						1						
- GRAND	O TOTAL -				1	1	1						
		·											

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN02LA025

Occurrence Date: 02/17/2002

Occurrence Type: Accident

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Joan D Peterson Aviation Safety Inspector - Operations FAA Flight Standards District Office 116 North 2400 West Salt Lake City, UT 84116